



Improved Back Jogger

Included in this TIP:

- All required parts
- Necessary engineering
- Updated documentation pages for relevant sections

Estimated downtime, no production:

- 5 days

Estimated startup, limited production:

- 3 day

Estimated monitoring in production:

- 2 day

Required manpower:

- 1 BW Papersystems Mechanical Field Service Engineer
- 1 Bw Papersystems Electrical Engineer
- Additional Assistance from Customers' Maintenance

(Additional local resources to be determined, if needed)

How can we help you? Please do not hesitate to contact us for any questions regarding our comprehensive Customer Service offerings:

TIPs/Upgrades:

- tips.zerand@bwpapersystems.com